

## **ENGINEERS & CONSULTANTS PVT. LTD.**









 Engineers • Architects • PMC for Repairs & Redevelopments • Valuers B8, Sai Aastha Chsl, Mulgi Nagar, Sai Baba Nagar, Borivali (West), Mumbai-400092.

Tel.: 28620757 Email: darvcpl@gmail.com

CIN NO. U74999MH2012PTC233296 • GST NO. 27AAECD3635P1Z9

Ref.: RPGN/012/03/02/2022

Date: 16/02/2022

To

The Trustees,

Cosmopolitan Education society,

D.N. Nagar, Andheri (W),

Mumbai - 400 053

## Sub: Structural Audit of Your Cosmopolitan Education society

Sirs.

With the reference to the above we wish to state that our company has undertaken the Structural Audit of your premises by virtue of Structural Licence held by Mr. Jaideep Desai associated with our company and a licensed Structural Engineer with MCGM Licence No STR / D / 147.

Thanking you

Yours truly

For DARV Engineers & Consultants Pvt. Ltd.,

Satish Rao

(Director)


Shri. Harshad C. Valia International School C.E. Society Road, D.N. Nagar,

Andheri (W), Mumbai-400053.

Manager

Shri. Harshad C. Valia International School C. E. Society Road, D. N. Nagar, Andheri (W), Mumbai-400053.









Engineers - Architects - PMC for Repairs & Redevelopm

A-9, Silver Arch, Haridas Nagar Junction, R. M. Bhattad Marg, Borivali (W), Mumbai - 400092. Tel.: 2862 0757. Email: darvcpl@gmail.com

Ref. No.: RU/JUN-21/1/2020

Date: 21st June 2020

To

The Trustees.

Cosmopolitan Education Society,

D. N. Nagar, Andheri(W)

Mumbai-53

Sub.: Structural Audit Report of School building of Cosmopolitan Education Society at above mentioned address. Bearing CTS No.195/199.

Respected Sir,

Brief background of buildings' structure:

As per Architectural drawings (available with Cosmopolitan Education Society records) shown to me, the building was constructed during 1984 or so. There were signs of previous repairs.

As requested by you. We have inspected the structure of the said building during February' 2020 and suggested that structural repairs need to be carried out by a contractor experienced in polymer, epoxy and micro concrete repairs.

Subsequently, repairs were carried out by an experienced contractor under day-to-day supervision by society appointed supervisor, and our guidance, in the form of periodic visits, as per contractor's requirements.

Further to our observations regarding multipurpose hall which is as below.

It is placed on ground floor & covered with AC sheet roofing supported by MS frame work. There is a false ceiling at bottom level of roof truss which is rested on lightweight frame work fixed to walls. Thus there is no extra load on roof frame work and hence no need to worry in this regard as structural stability is not disturbed.

This is to state that the repairs have been carried out as per standard engineering practice, and that the said school building is structurally stable and safe to be used for the purpose intended, to best of my knowledge. (Considering the age of the building and the history of earlier repairs and maintenance).

Following section is being run in the above mentioned school building:

1. Shri Harshad C. Valia International School

This certificate is being issued as per your request.

This certificate is valid for period of 3 years.

For DARV Engineers & Consultants Pvt. Ltd.

Ravindra Utagi **Director** CA/89/12132

Shri. Harshad C. Valia International School

C.E. Society Road, D.N. Nagar,

Manager

Andheri (W), Mumbai-400053. Shri. Harshad C. Valia International Schoo C. E. Society Road, D. N. Nagar, Andheri (W), Mumbai-400053.